


**Printware**

1175 Feeder Green Belt Bearing Squealing

Printware has noticed that the bearings of the green alignment belts of the 1175 feeder may exhibit a squealing noise or seize up completely. While the issue has been limited to a small number of machines thus far, we are extending the recommended procedure to all our customers.



Printware recommends that all customers use light-weight grease for the bearings. We use Super Lube Multi-Use Synthetic Oil, but you can use any similar light-weight grease.

- Apply a small amount of grease to the shaft near the bearings.
- Using the operator-side knobs, move the belts so the bearings pass over the greased area.
- Hit the “Jog” button located on the back of the feeder to run the belts and bearings.
- Repeat the greasing process as necessary until the belts run smoothly and quietly.
- You can follow along with our video on [Greasing the 1175/1175C Feeder Bearings](#)

We recommend that you grease the bearings bi-monthly or more often as needed. If you have any questions, please reach out to us at (800) 456-1400 EXT 2 or support@ijetcolor.com