



Service,
Construction
& Design

Electrical Survey

Survey Date 05/27/2021 10:25

Dispatch # **SAMPLE**

Status **Complete**

Tech 1

John Smith

Tech Email

example@directteam.com

Job/Loc Name	Job/Loc Address	Suite #	Job/Loc City
Acme Sample Supply	1234 Sample St	120	Houston

ELECTRICAL SERVICE

Incoming Service Voltage

240/120v, 1 Phase, 3 Wire

Service Wire Size

#6

Main OCP Amperage Size

100A

Transformer(s)

25 KVa, single phase, 240/480-120/240

Service Equipment Condition

Good

Grounding & Bonding Condition

Good

Electrical Service Files & Image Upload

- [CEF338FD-9](#)
[BFB-43CF-B6](#)
[2F-2F5727C8](#)
[0D88.jpeg](#)

INTERIOR LIGHTING

Office Lighting

4' T8 lamps (20)

Emergency Lighting

Good

Utility Lighting

Good

Warehouse Lighting

Closet has (2) 4' T8 lamps out

Warehouse office has (11) 4' T8 lamps out

Warehouse has (3) 8' F96 single pin T12 lamps out

Accent Lighting

Good

Int. Lighting Controls & Switching

Good

EXTERIOR LIGHTING

RECEPTACLES & EQUIPMENT WIRING

General Purpose Receptacles

Good

GFCI Devices

Good

Special Devices

Na

Pump Wiring

Power Poles

Good

Cubicle Wiring

Na

Appliance Connections

Good

Other Power Wiring

Good

Good

QUALITY & CODE COMPLIANCE

General Wiring Methods

Good

Disconnects & Fusing

Good

Panel Interiors

Good

Panel Schedules/ Labels Status

Panel Schedules Present

Communication & Data Cabling

Good

Panel Schedules/ Labels Comments

Good

SURVEY CHECKLIST

Lighting Systems

Inspected and documented visible outages
Inspected and documented visible wiring quality
Inspected and documented switching operation
Inspected and documented tripped breakers
Inspected and documented Emergency Lighting

Power Systems

Inspected and documented receptacles
Inspected and documented exposed wiring
Inspected and documented missing face plates
Inspected and documented polarity
Inspected and documented proper GFCI locations
Inspected and documented proper GFCI operation

GENERAL SURVEY COMMENTARY & RECOMMENDATIONS

QUALITY CONTROL MEASURES

Quality Control Measures

Checked IN and OUT w/ Client
Worked Safe
Cleaned Up Job Site
Locked Up Doors and Hatches

This Electrical Survey was completed by Direct Service, Construction & Design | 713.672.9345 | www.directteam.com |
TECL #17117

Dispatch #

SAMPLE

End of Survey

Survey Date

05/27/2021 10:25