



Plumbing Survey

Current Date / Time 05/17/2021 07:46

Tech 1

John Smith

Dispatch #

SAMPLE

Tech Email

example@directteam.com

Status Complete

Job/Loc Name Job/Loc Address Suite # Job/Loc City
Acme Sample Supply Co 5555 Sample Blvd 120 Houston

PLUMBING FIXTURES

Sink(s)

Area Served	Location Notes	Condition	Mount
Unisex	In the breakroom to the right	Good	CT
Breakroom	Straight back	Good	CT

Faucet(s)

Area Served	Location Notes	Condition	Hot Water?
Unisex	In breakroom first door to the right	Good	Yes
Breakroom	Straight back	Good/needs aerator	Yes

Toilet(s)

Area Served	Location Notes	Condition	Mount	Flush
Unisex	In breakroom to the right	Good	FM	Tank

Urinal(s)

Area Served	Location Notes	Condition
	N/A	

Floor Drain(s)

Area Served	Location Notes	Condition	Primer/Guard?
	N/A		

Hose Bib(s)

Area Served	Location Notes	Condition	Vacuum Breaker?
Interior	By door leading to offices	Good	Yes

APPLIANCES

Water Heater(s)

Heating Source	Voltage	Location Notes	Condition	Model #
Electric	120v	Above unisex bathroom, easily accessible from office next	Decent	Unable to read information plate

Appliance Files & Image Upload

- [08A46D54-2C71-4FAC-9F18-3C59767821D0.jpeg](#)
- [46C610EE-225A-4456-B6CF-360F1BD4C278.jpeg](#)

PUMPS

WATER MAINS

Water Main(s)

Type	Size	Length	Height	Rpr Clamps?	Location Notes	Condition
Galvanized	2"	80	27	No	Midway through space, turns to copper without dielectric unions	Decent

GAS SYSTEMS

Gas Survey

Gas Present?	Meter Present?	Size	Location Notes	Condition
No				

QUALITY & CODE COMPLIANCE

Plumbing System Quality and Code Compliance Comments

Replace aerator on breakroom sink

SURVEY CHECKLIST

Water Systems

Inspected and documented visible water color/odor issues
 Inspected and documented visible water lines
 Inspected and documented visible supply lines

Gas Systems

Inspected and documented visible gas piping conditions
 Inspected and documented visible p-traps
 Inspected and documented visible vent piping

Sewer Systems

Inspected and documented visible p-traps

GENERAL SURVEY COMMENTARY & RECOMMENDATIONS

QUALITY CONTROL MEASURES

Quality Control Measures

Checked IN and OUT w/ Client
Worked Safe
Cleaned Up Job Site
Locked Up Doors and Hatches

This Plumbing Survey was completed by Direct Service, Construction & Design | 713.672.9345 | www.directteam.com | MPL#37872

Dispatch #

SAMPLE

End of Survey

Current Date /
Time

05/17/2021 07:46